

Permit Services Report

Permit Number 2021-PP-0 [REDACTED]

Owner

[REDACTED]
[REDACTED]
[REDACTED]

Municipality: Regional Municipality of Wood Buffalo

Permit Issued: 3/17/2021

PSR Issued: 3/19/2021

Installation Address: [REDACTED]

Lot: [REDACTED] **Block:** [REDACTED] **Plan:** [REDACTED]

Contractor

[REDACTED]

Permit Type: Residential Plumbing for Single Detached - Contractor

Desc. of Work: COMPLETE THE INSTALLATION OF A
BACKWATER VALVE IN BASEMENT OTHER FIXTURE

Status

Compliance monitoring services have been provided as required by the Safety Codes Act, and codes, regulations and policies pursuant to the Act. It is the opinion of the issuer of this report that:

Work complies with the intent of the Safety Codes Act and applicable regulations.

Work may not comply as:

- A Safety Codes Officer was unable to gain entry for the required site inspection(s).
- The permit expired
- The permit was cancelled
- Deficiencies must be corrected

For the work to meet the intent of the Safety Codes Act applicable regulations, please contact the Municipality within 30 days of this report if you wish to make arrangements to verify that deficiencies are corrected.

Note: This report remains on file as record of compliance or non-compliance with the provisions of the Safety Codes Act, regulations, Codes, and standards. Pursuant to the Safety Codes Act, the "Owner" is responsible for meeting the requirements of the Act.